



Zigmont Magic F/X, Inc.

Providing All Special Effects

www.effectspecialist.com

www.zigmont.com

Phone 813.689.6269

zigmont@zigmont.com

Fireworks – Propane Flames – CO2 Blasts – Confetti – Snow
Exploding Balloon Walls – Wind – Smoke Effects – Pyrotechnics

Thank you for renting a Snowmasters snow machine. Each machine needs 15 amps to run, AC cord loses 1 amp every 20 feet.
PLEASE PAY ATTENTION AS THE MACHINE IS PACKED FOR REPACKING

You will find the snow machine with a weather cover, once taken out of the case you will need to assemble the hanging bar/floor plate with c clamps attached. You have a safety cable as well. You can leave this machine out in light rain, but you should run it in rain. You should have a ground fault for outdoor use.



You will need to mix the each concentrate mix with one gal distilled water for each in the bottle in back of the machine.

You can use the dial 30 foot controller or the DMX dial can run flake sizes 800-899, OR JUST RUN dmx 000- 512

Make sure the hose is all the way down into the bottle.

Please remove all snow fluid from the bottles before shipping. Do not return with fluid in bottles, as this will damage the machines.

Please repack machines as they were packed.

Please label the machines and they are schedule for pick up.